

# **Wall Max**

### PARTS:



#### HARDWARE:



5/16" Stopnut



5/16" Washer







1/4" Washer

## TOOLS:


- 7/16" Socket
- Drill
- Tape Measure
- Pencil


Begin by unpacking all boxes and locating the hardware

Locate a Wall Mount Plate and lay down with pems facing up.




(Optional) If you have a Guard, place the top holes onto the Wall Mount Plate pems.






Next, align the two top holes of the Wall Max with the pems on the Wall Mount Plate. Secure using (2) 5/16" Washers and (2) 5/16" Stopnuts.



Secure the Wall Max to the wall using 1/4" x 2" Lag Bolts and 1/4" Washers.



# SPACING RECOMMENDATIONS:

We recommend 16" on-center spacing between racks



